# 2-Axis High Speed Interpolation/Normal Motion Controller

### Features

- Independent 2-Axis controlling with high operating speed of max. 4Mpps
- Linear/Circular interpolation control (PMC-2HSP)
- Realizing a wide variety of operation up to 200 steps using 17 control commands combination (13 commands except circular/linear interpolation command for PMC-2HSN series)
- Various control interface available (USB, RS232C, RS485, Parallel I/F)
- Controlling up to 32 axes (16 units)
   via RS485 serial communication (Modbus RTU)
- 4 operation modes: Jog, Continuous, Index, Program mode
- Symmetrical/asymmetrical trapezoid, S-shaped de/acceleration driving function PMC-2HS-USB





PMC-2HS

Please read "Caution for your safety" in operation manual before using.



 $\mathbb{Q}$ 

(except for PMC-2HS 485)


#### User Manual

- Please refer to user manual for detailed instructions and specifications.
- Visit our web site (www.autonics.com) to download user manual and software [MotionStudio].
- User manual describes installing software, setting parameter and program, operation mode, and multi-axis operation, etc. to operate motion controller.

## ■ Software (MotionStudio)

MotionStudio is the windows software designed to operate motion control for PMC-2HSP/2HSN series.

- Compatible Microsoft Windows 98, NT, 2000,
   XP (32-bit, 64-bit), Vista (32-bit, 64-bit) and 7 (32-bit, 64-bit)
- Supports 9,600, 19,200, 38,400, 57,600, 115,200 bps transmission speeds
- Available to use on all OS supported COM ports (COM1 to COM256)
- Multilingual support (korean, english)
- Provides a calculator for convenience (calculates PPS, center of interpolation, end coordinates)



## Specifications

Ordering Information

| Model                |                     | PMC-2HSP-USB   | PMC-2HSP-485                       | PMC-2HSN-USB                     | PMC-2HSN-485                       |  |
|----------------------|---------------------|--|------------------------------------|----------------------------------|------------------------------------|--|
| Control axis         |                     | 2-Axis   |                                    |                                  |                                    |  |
| Motor for control    |                     | Pulse string input stepper motor or servo motor  |                                    |                                  |                                    |  |
| Power supply         |                     | 24VDC  |                                    |                                  |                                    |  |
| Power co             | onsumption          | Max. 6W  |                                    |                                  |                                    |  |
| Inposition           | n range             | -8,388,608 to 8,388,607 (selectable absolute/relative value, available pulse-scaling function)   |                                    |                                  |                                    |  |
| Range fo             | r the drive speed   | 1 pps to 4 Mpps (1 to 8,0  | 00pps × Magnification 1 to 5       | 500)                             |                                    |  |
| Pulse out            | tput mode           | 1 Pulse/2 Pulse output (li   | ne driver output)                  |                                  |                                    |  |
| Operation            | n mode              | Jog / Continuous / Index   | / Program                          | ·                                |                                    |  |
| Index ste            | p numbers           | 64 steps per each axis   |                                    |                                  |                                    |  |
|                      | Step                | 200 steps  |                                    |                                  |                                    |  |
| Program              | Control             | ABS, INC, HOM, LID*1, CID*1, FID*1, RID*1, TIM, JMP, REP, RPE, ICJ, IRD, OPC, OPT, NOP, END  |                                    |                                  |                                    |  |
| function             | Start               | Power On program auto-start function   |                                    |                                  |                                    |  |
|                      | Home search         | Power On home search auto-start function   |                                    |                                  |                                    |  |
| Home se              | arch mode           | High speed near home search (step 1) $\rightarrow$ Low speed home search (step 2) $\rightarrow$  |                                    |                                  |                                    |  |
| 1101110 30           |                     | Encoder Z phase search (step 3) → Offset move (step 4)   |                                    |                                  |                                    |  |
| I/O                  |                     | Parallel I/F (CN3): 13 inputs, 4 outputs  X-axis (CN 4) / Y-axis (CN 5): 8 inputs, 6 outputs (general-purpose I/O, two of each)                                    |                                    |                                  |                                    |  |
| Environ              | Ambient temperature | 0 to 45°C, storage: -15 to   | 70°C                               |                                  |                                    |  |
| -ment                | Ambient humidity    | 20 to 90%RH  |                                    |                                  |                                    |  |
| Accessory            |                     | [Common] Power connector, I/O connector (PI/F, X-axis, Y-axis),     RS232C communication cable (1.5m): 1, User Manual     [USB type] USB communication cable 1m: 1 |                                    |                                  |                                    |  |
| Weight <sup>*2</sup> |                     | Approx. 344g<br>(approx. 101.5g)   | Approx. 308.7g<br>(approx. 101.6g) | Approx. 344g<br>(approx. 101.5g) | Approx. 308.7g<br>(approx. 101.6g) |  |

X1: These commands are only for PMC-2HSP series.

Q-58 Autonics

<sup>\*</sup>Environment resistance is rated at no freezing of condensation.

# 2-Axis High Speed Interpolation/Normal Motion Controller

# **■** Standard Operation Method

There are three methods to operate the motion controller.

Operation by PC

Connect a PC and the controller with communication cable and run dedicated program (MotionStudio).

• Operation by Parallel I/F

Connect a sequence controller or switch to Parallel I/F.


Operation by serial communication (dedicated communication protocol)
 Using serial communication protocol, operate according to program writing by user.

### Program Commands

| Command type   | Code | Description                               |
|--|------|---|
|  | ABS  | Move absolute position                    |
|  | INC  | Move relative position                    |
|  | НОМ  | Home search                               |
| Drive commands   | LID  | 2-Axis linear interpolation <sup>*1</sup> |
|  | CID  | 2-Axis CW circular interpolation**1       |
|  | FID  | 2-Axis CW arc interpolation*1             |
|  | RID  | 2-Axis CCW arc interpolation**1           |
|  | ICJ  | Jump input condition                      |
| 1/0  | IRD  | Stand-by external input                   |
| I/O commands   | OPC  | ON/OFF output port                        |
|  | OPT  | ON pulse from output port (period)        |
|  | JMP  | Jump                                      |
| December of the land of the la | REP  | Start repetition                          |
| Program control commands   | RPE  | End repetition                            |
|  | END  | End program                               |
| Other  | TIM  | Timer                                     |
| Others   | NOP  | No operation                              |

※1: These commands are only for PMC-2HSP series

## Unit Descriptions



#### 1. Power / Status indicator

Used to indicate power, controller's communication status and operation status for each axis

#### 2. Power connector terminal

Used to connect power for controller

#### 3. RS232C connector terminal

Used to connect RS232 serial (RJ12-DSUB9) connection cable

#### 4. USB/RS485 connector terminal

Used to connect USB and RS485 connection cable

#### 5. External I/O connector terminal


Used to operate various drives through input and output of Parallel I/F, X, Y

#### 6. ID select switch


Used to set unique ID for each node in case of RS485 communication

#### ○ I/O terminal

### • PMC-2HS□-USB



#### PMC-2HS□-485



| Connector No. | Description                        |  |  |
|---------------|------------------------------------|--|--|
| CN1           | Power connector                    |  |  |
| CN2           | RS232C connector                   |  |  |
| CN3           | Parallel I/F connector             |  |  |
| CN4           | X-Axis I/O connector               |  |  |
| CN5           | Y-Axis I/O connector               |  |  |
| CN6           | PMC-2HSP/2HSN-USB: USB connector   |  |  |
| CINO          | PMC-2HSP/2HSN-485: RS485 connector |  |  |
| IDS           | ID selection switch                |  |  |

(A) Photoelectric Sensors

(B) Fiber Optic

> (C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encoders

(G) Connectors/ Connector Cables/ Sensor Distribution Boxes/Sockets

Temperature Controllers

(I) SSRs / Power Controllers

Counters

Meters

Speed / Pulse Meters

Units

(O) Sensor Controllers

(P) Switching Mode Power Supplies

(Q) Stepper Motors & Drivers & Controllers

(R) Graphic/ Logic Panels

(S) Field Network


(T) Software

Autonics Q-59

# PMC-2HSP/PMC-2HSN Series

# **■** Power Connector (CN1)


|         | Pin No. | Signal name |
|---------|---------|-------------|
| 1 24VDC |         | 24VDC       |
| Ì       | 2       | GND (0V)    |



# ■ RS232C Connector (CN2)

| Pin No. | Signal name | Input/Output | Description       |
|---------|-------------|--------------|-------------------|
| 1       | TXD         | Output       | Receiving data    |
| 2       | RXD         | Input        | Transmitting data |
| 3       | GND         | _            | Ground            |
| 4       | _           | _            | No-connection     |
| 5       | _           | _            | No-connection     |
| 6       | _           | _            | No-connection     |

%The internal connection diagram of RS232C communication cable is shown as below.



# ■ Parallel I/F Connector (CN3)


The Parallel I/F connector which is connected with a sequencer or mechanical contacts operates motion controller same as PC program. When input signal is ON, the input signal terminal and GEX terminal are connected by mechanical contacts or open collector output and open collector output transistor is ON when the output signal is ON.


| Pin No. | Signal name         | Input/Output | Description                                  |
|---------|---------------------|--------------|--|
| 1       | RESET               | Input        | Reset  |
| 2       | HOME                | Input        | Home search start command                    |
| 3       | STROBE              | Input        | Drive start command                          |
| 4       | X/JOG Y+            | Input        | X-axis designate/Jog Y+                      |
| 5       | Y/JOG Y-            | Input        | Y-axis designate/Jog Y-                      |
| 6       | STEPSL0/RUN+/JOG X+ | Input        | Register designate 0/Run+/Jog X+             |
| 7       | STEPSL1/RUN-/JOG X- | Input        | Register designate 1/Run-/JogX-              |
| 8       | STEPSL2/SPD0        | Input        | Register designate 2/Drive speed designate 0 |
| 9       | STEPSL3/SPD1        | Input        | Register designate 3/Drive speed designate 1 |
| 10      | STEPSL4/JOG         | Input        | Register designate 4/Jog designate           |
| 11      | STEPSL5/STOP        | Input        | Register designate 5/Drive stop              |
| 12      | MODE0               | Input        | Operation mode designate 0                   |
| 13      | MODE1               | Input        | Operation mode designate 1                   |
| 14      | X DRIVE/END         | Output       | X-axis drive/Drive end pulse                 |
| 15      | Y DRIVE/END         | Output       | Y-axis drive/Drive end pulse                 |
| 16      | X ERROR             | Output       | X-axis error                                 |
| 17      | Y ERROR             | Output       | Y-axis error                                 |
| 18      | GEX                 | 0V           | Ground                                       |
| 19      | GEX                 | 0V           | Ground                                       |
| 20      | VEX                 | +24V         | Power supply for sensor (24VDC, Max. 100mA)  |

Q-60 Autonics

# 2-Axis High Speed Interpolation/Normal Motion Controller

# **■** Input/Output Connections (CN3)






< CN3 control output connections >

## X, Y-Axis Input/Output Connector (CN4, CN5)

CN4 and CN5 are I/O signals for X-Axis and Y-Axis respectively.


The pin arrangement of CN4 and CN5 are equal. 'n' in the table means X for CN4 and Y for CN5.

| Pin No. | Signal name | Input/Output | Description                                 |
|---------|-------------|--------------|---|
| 1       | n P+P       | Output       | Drive pulse in the CW + direction           |
| 2       | n P+N       | Output       | Drive pulse in the CW + direction           |
| 3       | n P-P       | Output       | Drive pulse in the CCW - direction          |
| 4       | n P-N       | Output       | Drive pulse in the CCW - direction          |
| 5       | n OUT0      | Output       | General output 0                            |
| 6       | n OUT1      | Output       | General output 1                            |
| 7       | n IN0       | Input        | General input 0                             |
| 8       | n IN1       | Input        | General input 1                             |
| 9       | n STOP2     | Input        | Encoder Z-phase                             |
| 10      | n STOP1     | Input        | Home  |
| 11      | n STOP0     | Input        | Near Home                                   |
| 12      | n LMT+      | Input        | + direction limit                           |
| 13      | n LMT-      | Input        | - direction limit                           |
| 14      | EMG         | Input        | Emergency stop                              |
| 15      | GEX         | 0V           | Ground                                      |
| 16      | VEX         | +24V         | Power supply for sensor (24VDC, Max. 100mA) |




XCN4, 5 input/output is same as CN3 input/output connections.

Drive pulse output of motion controller which is inputted to motor driver is line driver output.



< Example of Motor driver connection >



< Example of limit and HOME sensor connection >

(A) Photoelectric Sensors

(B) Fiber Optic

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

> (F) Rotary

(G) Connectors/ Connector Cables/ Sensor Distribution Boxes/Sockets

(H) Temperature Controllers

(I) SSRs / Power Controllers

(J) Counters

> K) imers

(L) Panel Meters

(M) Tacho / Speed / Pulse Meters

> l) isplay nits

O) Sensor Controllers

(P) Switching Mode Power Supplies

(Q) Stepper Motors & Drivers & Controllers

(R) Graphic/ Logic Panels

(S) Field Network Devices

(T) Software

Autonics Q-61


# PMC-2HSP/PMC-2HSN Series

# ■ RS485 Connector (CN6)

| Pin No.1 | Signal name | Input/Output | Description                   |
|----------|-------------|--------------|-------------------------------|
| 1        | B (-)       | I/O          | Transmitting / Receiving data |
| 2        | A (+)       | I/O          | Transmitting / Receiving data |
| 3        | G           | _            | <b>*1</b>                     |




## Connections




<sup>&</sup>lt; Basic configuration of the motion controller (Configuration only for X-axis) >

## Dimensions

(unit: mm)





Q-62 Autonics

X1: Connect the ground when it is required depending on communication environments.